MARION COUNTY SURVEYOR'S OFFICE SECTION CORNER RECORD DEBRA S. JENKINS BRYAN F. CATLIN, PLS SEC. 16 TWN. 17_{N} RNG. 2_{E} MARION COUNTY SURVEYOR TECHNICAL SUPERVISOR W 96th St. 9600 N Date: 6-26-09 Party Chief: Greene Crew: Taylor Type of Marker: MCSO capped rebar fd 3" down Method of Establishment: County: 4-4-1997 Section Line IN S.P.C. E Zone, NAD 83 Name: 17021601 N: 519 305.656 5(m) E: 44 433.836 3(m)

W 96th St. 9600 N

114.37

192.80'

2.

PWP

1.

Address 8723

Address 8639

Note: Corner is 1.32' West of the east rail

Corner originally set as a post in 1821 by Wm. B. Laughlin with the following witnesses: 8"beech bearing N 83 E 4 links and a 12" dogwood bearing N 80 W 28 links (Marion County Atlas p. 4). A survey by Percy Hasbrook on November 12, 1849 indicates no stone and both witnesses gone (Pike Legal Book p. 40). Corner referenced by Miller on 7/20/1977 and called a rebar. Corner was excavated on 9/28/81 by Wilcoxen and no stone or sub-surface mark was found. A rebar was set. Corner referenced by Greene on 3/9/88 and called a rebar. Corner referenced by Wilcoxen on 4/4/1997 and called a capped rebar found. Corner referenced by Wilcoxen on 4/6/2002 and called a MCSO capped rebar found 3" down. Corner referenced by Greene on 6/26/09 and called a MCSO capped rebar.

REF.	DISTANCE	DESCRIPTION
1.	192.80'	Road nail N PwP #37-151 X 18" up
2.	114.37'	Road nail N PwP #38-151 X 24" up
3.	59.57'	Mag nail w/shiner SW walnut 12" up
4.	23.53'	Cut 'x' W side storm drain